ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Atturu

Street ID
W0645, W0356, W0352, W0631, W0336, W0342, W0346, W

Street Name
4th Crs, NA, R H B Colcny, 6th Crs, R H B Colcny, 7th Crs, 2nd Crs

Significant Landmark
Akshayanagara 1st main and cross roads

Segment No.
3/C-W0645/S102735

Total Length (m)
477.36

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	62.04	77.563710	13.100060	77.563476	13.099548	W0330	W0342
2	75.60	77.563750	13.100063	77.564423	13.099885	W0645	W0631
3	78.91	77.563624	13.099773	77.564321	13.099569	W0645	W0631
4	66.38	77.563664	13.099462	77.564249	13.099285	W0645	DEAD END
5	64.08	77.563581	13.099163	77.564144	13.098988	W0645	DEAD END
6	65.10	77.563484	13.098870	77.564064	13.098716	W0645	DEAD END
7	65.25	77.563401	13.098557	77.563980	13.098397	W0645	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work
Asphalting to Roads and Improvements to Drain in Akshayanagara 1st main and cross roads in ward no 03 Yelahanka Satellite Town Sub division Yelahanka

Sanctioned Estimated Amount (Rs.)
5000000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Asphalting

Other Work Type

Tender
Not a Tender

Work Details
Asphalting to Roads and Improvements to Drain in Akshayanagara 1st main and cross roads in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Job No. / Work Code
003-17-000008

Work Order No.
BBMP/EE (YNK.D) /WO/140/2017 -18

Work Order Date
31/03/2017

Period of Extention
90 DAYS

Defect Liability Period From
30/04/2017

Defect Liability Period To
29/04/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
12		CHANDRAKANTH
Date of Inspection	**Remarks**	
24/05/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0645, W0356, W0352, W0631,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/05/2017	23/06/2017	COMPLETED
SE	VASU K M	24/05/2017	23/06/2017	COMPLETED
EE	VASU K M	24/05/2017	23/06/2017	COMPLETED
AEE	ASHOK	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED
AE	CHANDRAKANTH	24/05/2017	23/06/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0645, W0356, W0352, W0631,